

Visual Home Inspection

123 Sample Estates Dr
Manchester, Missouri 63021

Prepared for :
Kristin Sample



Inspected by :

Chad W. Borah
Pillar To Post - STL
66 St. Charles Place
St. Louis, Missouri. 63119

Phone: (314) 645-7871 Fax: (314) 645-6595. Email: chad@stlinspections.com

Property And Site



Ivy growing behind siding.

Roof Structure



Two layers.



General condition of roof covering.

Attic



Evenly distribute insulation. Bathroom exhaust properly vented to exterior.

Electrical Service/Panel



FPE Stab-Lok panel.

Basement/Structure



Moisture entry (SE Corner).